

Menu

HISTORY FILE MAP for year 2007

REALTIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

152.08:39-09:52 1hr 13m realtime 512 bps lost on DSS-75 due to rain.
152.13:54-14:12 18m realtime 512 bps lost on DSS-75 due to rain.

150.14:22-14:27 5m realtime 512 bps lost on DSS-14 due to late acquisition. DR G107777 refers.



155.08:42-10:30 1h 48m realtime 512 bps lost on DSS-75 due to antenna servo problems.
155.13:50-13:58 8m realtime 512 bps lost due to planned gap between DSS-75 and DSS-24.

154.13:46-14:04 18m realtime 512 bps lost due to planned gap between DSS-75 and DSS-24.
154.23:22-23:37 15m realtime 1024 bps lost on DSS-43 due to antenna keyhole.